



The tool is designed for trimming, stripping insulation from cables and crimping telecommunication plugs (plug types see below)



Instruction:

- 1 Squeeze the handles and open the lock.
- 2 Cut the cable to the required length. Be sure to cut at a right angle, and not diagonally.
- 3 Insert the flat cable between the blades to remove the insulation.
Try to keep the cable perpendicular to the knives, squeeze the handles, pull the cable out of the tool.
- 4 To remove the external insulation from the round cable, place it in a round profile, squeeze the handles and twist the cable around its axis.
- 5 Remove the external insulation, insert the conductors into the plug, make sure they are in the correct position
- 6 6. Insert the plug with the cable into the appropriate socket socket in the tool.
Make sure that the conductors are strictly between the tool press and the gold-plated contacts of the plug.
Squeeze the handles as far as they will go.

